



# Harmful Algal Bloom (HAB) Satellite Imagery NOAA – NOS, Copernicus Sentinel-3a

This data product is experimental. Cyanobacteria detections should be confirmed and may not indicate presence of cyanotoxins.

Learn more about HABs at [ohioalgaefinfo.com](http://ohioalgaefinfo.com)

Find beach advisories and sampling data at <http://publicapps.odh.ohio.gov/beachguardpublic>

## Chippewa Lake MEDINA COUNTY

Satellite Image Taken: 04/28/2022  
V2 PROCESSING & COLOR RAMP

- Public Water System Intake
- ODNR Sample Sites



[EPAHABmailbox@epa.ohio.gov](mailto:EPAHABmailbox@epa.ohio.gov)

Report Date: 05/02/2022