



**Harmful Algal Bloom (HAB) Satellite Imagery**  
**NOAA - NOS, Copernicus Sentinel-3**

This data product is experimental. Cyanobacteria detections should be confirmed and may not indicate presence of cyanotoxins.

Learn more about HABs at [ohioalgaefinfo.com](http://ohioalgaefinfo.com)  
 Find beach advisories and sampling data at <http://publicapps.odh.ohio.gov/beachguardpublic>

**Chippewa Lake**  
**MEDINA COUNTY**

*Satellite Image Taken: 07/25/19*

- 🕒 PWS Active Intakes
- ▲ ODNR Sample Sites



[EPAHABmailbox@epa.ohio.gov](mailto:EPAHABmailbox@epa.ohio.gov)

*Report Date: 7/26/2019*